Amendments to the Specification:

Please replace paragraph [0006] with the following rewritten paragraph:

[0006] Though information such as an from an amusement facility and pachinko parlor can be collected via the Internet before going to an arcade, the information information concerning gaming machines in the arcade or the like has not often been acquired directly by using a mobile terminal or the like in the arcade.

Please replace paragraph [0007] with the following rewritten paragraph:

[0007] Usually, an individual collects information only sporadically, for example, by retrieving <u>information from various</u> sites via the Internet while using own cellular phone or the <u>like so as to like to collect</u> information items site by site. No system has been known which makes it possible to acquire information in various places such as amusement facilities, arcades, and restaurants and exchange information by using a mobile terminal.

Please replace paragraph [0008] with the following rewritten paragraph:

[0008] The system providing information specific to individuals cannot operate without a dedicated card. Under the current circumstances where various kinds of cards exist, a user must choose and present an appropriate card from among a number of own cards. This complicates the management and utilization of cards, and necessitates a signup procedure each time the card is issued, whereby paperwork in various facilities becomes troublesome as well. Also, it takes time and cost and expense to introduce such a system.

Please replace paragraph [0010] with the following rewritten paragraph:

[0010] However, the floor staff member of the arcade not only monitors false deeds as mentioned above, but also carries out various works to mend the shortage of changes in money changers, card issuing machines, and the like, and the clogging with balls, attaches a plate to the gaming machine at the time of a jackpot, and transports gaming media, for example. The floor staff member is busily running around the arcade for these works. When

the shortage of ehanges change or the like occurs in a money changer, a card issuing machines, and the like, players may feel a have a bad impression or sense of discomfort with respect to the areade in particular. arcade. Therefore, the shortage of ehanges change or the like must be mended rapidly which is one of cumbersome works for corrected rapidly. This is one of the cumbersome jobs of the floor staff member. Unlike the clogging with balls occurring which occurs unexpectedly, the shortage of changes of change or the like can be prevented from occurring by seeing knowing the amount of money in money changers, card issuing machines, and the like. In practice, however, it is difficult for the floor staff member busily running around the arcade to carry out such an operation.